



RTR Services Inc.
DUMP TRUCK
CONDITION REPORT

RTR #: 8103701

ACCOUNT NUMBER:
ACCOUNT NAME:

YEAR:	2003	MILES	417,259	VIN#:	2FZHAZCV93AL96209				
MAKE:	Sterling	GVW:	82,000	BED HEIGHT	66"	BED LENGTH	17'	BED WIDTH	96"
MODEL:	L9500	WHEELBASE:	150"	COLOR: EXTERIOR:	Red	INTERIOR:	Tan		
ENGINE:	Mercedes 12.8L	HP		KEYS: IGNITION:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		DOOR: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		
TRANS:	8LL	FUEL:	<input type="checkbox"/> GAS <input checked="" type="checkbox"/> DIESEL	ANTIFREEZE TESTED:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		RATING:	32°	
DOES MOTOR RUN?	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	CAN IT BE DRIVEN?	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		COLLISION DAMAGE?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			

PHYSICAL APPEARANCE

	GD	FR	PR	N/A	COMMENTS	OPTIONS
BODY	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> PWR STEERING
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> BRAKES
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> AIR
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> HYD
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> PWR LOCKS
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> PWR WINDOWS
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Chip at lower by handle, scratches, dings	<input type="checkbox"/> PWR SEATS
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> PWR MIRRORS
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> AIR CONDITIONER
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> AIR RIDE SEAT D/P D
TIRES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	% 95 SIZE: 315/80 R22.5	<input checked="" type="checkbox"/> AIR RIDE SUSPENSION
	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	% 20/10 SIZE: 11R24.5	<input checked="" type="checkbox"/> AM FM RADIO
	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	% 20/10 SIZE: 11R24.5	<input checked="" type="checkbox"/> TAPE / CD / CB? <u>CD</u>
	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	% 5 SIZE: 315//80 R22.5	<input type="checkbox"/> HITCH TYPE _____
	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	% 30/20 SIZE: 11R24.5	<input checked="" type="checkbox"/> TARP SYSTEM
	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	% 20/10 SIZE: 11R24.5	<input checked="" type="checkbox"/> TANDEM AXLE
	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	% 0/30 SIZE: 11R 22.5 (info for tag axle)	<input checked="" type="checkbox"/> ENGINE BRAKE
GLASS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> TOOL BOX _____
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> FUEL TANKS
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> SINGLE GAL <u>70</u>
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> DUAL GAL _____
INTERIOR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Dirty, stained	<input checked="" type="checkbox"/> MUD FLAPS
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Stained, worn	<input type="checkbox"/> WHEELS
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> ALUMINUM
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Stained, vinyl	<input checked="" type="checkbox"/> STEEL
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Normal expected wear & tear, missing tarp	<input type="checkbox"/> BUD
MECHANICAL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> SPOKE
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> EXHAUST S/D? <u>S</u>
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> SUSPENSION
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> AIR
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> SPRING
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> PAD
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> LIFT/TAG AXLE
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> ARTICULATED
COMMENTS:						<input type="checkbox"/> BED CAPACITY _____
Stalls at idle						<input checked="" type="checkbox"/> WET KIT
Weak, slow crank						

COMMENTS: Tires are all mis-matched. Rear passenger front drive axle hub seal/cap leaking inside wheel. Only 1 wheel mounted on the tag axle. Unit has air leak, tag axle drops after sitting for a few hours. Left lift axle no yoke. Mileage unverified.

11/6/18

EMPLOYEE'S FULL NAME (PLEASE PRINT) _____ DATE _____ EMPLOYEE'S SIGNATURE _____
By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.