RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT				RTR #:	8123292
				ACCOUNT	
				ACCOUNT NAME:	
YEAR:	2011				
MAKE:	Roadhog	☐ YES ☒ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY		
MODEL:	RH4060	☒ OPERATIONAL			
SN:	1109020	☐ NON OPERATIONAL			
POWER:	Diesel	☐ UNTESTABLE			
DESCRIPTION:	Asphalt grinding unit that mounts to skid steer				
SHOT / COUNT / HOUR: Unknown					
NOTES / COMMENTS: Runs with jump start. Needs battery. Hours unverified.					

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT				RTR #:	
				ACCOUNT	
				ACCOUNT NAME:	
YEAR:					
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY		
MODEL:		☐ OPERATIONAL			
SN:		☐ NON OPERATIONAL			
POWER:		☐ UNTESTABLE			
DESCRIPTION:					
SHOT / COUNT / HOUR:					
NOTES / COMMENTS:					

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT				RTR #:	
				ACCOUNT	
				ACCOUNT NAME:	
YEAR:					
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY		
MODEL:		☐ OPERATIONAL			
SN:		☐ NON OPERATIONAL			
POWER:		☐ UNTESTABLE			
DESCRIPTION:					
SHOT / COUNT / HOUR:					
NOTES / COMMENTS:					

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107