RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	9013250-01
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:	2015			
MAKE:	Rayco	☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	RG40T	☒ OPERATIONAL		
SN:	0280915	☐ NON OPERATIONAL		
POWER:	Gas	☐ UNTESTABLE		
DESCRIPTION:	power stump grinder			
SHOT / COUNT / HOUR: 1119.2				
NOTES / COMMENTS: throttle cable broken, hours unverified				

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:				
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:		☐ OPERATIONAL		
SN:		☐ NON OPERATIONAL		
POWER:		☐ UNTESTABLE		
DESCRIPTION:				
SHOT / COUNT / HOUR:				
NOTES / COMMENTS:				

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #:	
			ACCOUNT	
			ACCOUNT NAME:	
YEAR:				
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:		☐ OPERATIONAL		
SN:		☐ NON OPERATIONAL		
POWER:		☐ UNTESTABLE		
DESCRIPTION:				
SHOT / COUNT / HOUR:				
NOTES / COMMENTS:				

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107